



**Manual Addendum: Included motor
P-39 Airacobra 1.2m**

EFL9150, EFL9175

The manual for the P-39 Airacobra 1.2m incorrectly states on pages 3, 18, 32 and 46, the BL15 Brushless Outrunner 880Kv (EFL8463) is installed in the aircraft.
BL15 brushless outrunner 850Kv (EFLM4115) is the correct motor installed in the aircraft.