

| Product • Produkt • Produit • Prodotto | DX6 | DX7G2 | DX7s | DX8 | DX9 | DX18 DX180Q | DX18G2 DX18 SE | DX10t DX18t | STi | TM1000 | TM1100 |
|---|-----|-------|------|-----|-----|----------------|-------------------|----------------|-----|--------|--------|
| Receiver Batt Energy Sensor (SPMA9604) | ✓ | ✓ | ✗ | ✗ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| Flight Pack Batt Energy Sensor (SPMA9605) | ✓ | ✓ | ✗ | ✗ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| High Current Sensor (SPMA9590) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| Variometer Sensor (SPMA9589) | ✓ | ✓ | ✗ | ✓* | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| GPS Sensor (SPMA9587) | ✓ | ✓ | ✗ | ✗ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| 40G 3-Axis G-Force Sensor (SPMA9586) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| 8G 3-Axis G-Force Sensor (SPMA9585) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| JetCat Sensor (SPMA9584) | ✗ | ✗ | ✗ | ✗ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| Altimeter (SPMA9575) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| Airspeed Indicator (SPMA9574) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |
| Temperature Sensor (SPMA9571) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Volt Pack Sensor (SPMA9570) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| RPM Sensor and Bracket (SPMA9569) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Brushless RPM Sensor (SPMA9558) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Deans Volt Sensor (SPMA9557) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| EC3 Volt Sensor (SPMA9556) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| JST Volt Sensor (SPMA9555) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Z Connector Volt Sensor (SPMA9554) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| PowerBox 12K DSMX Combo (PBS4850) | ✗ | ✗ | ✗ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✗ |

*Compatible with DX8 as Altimeter only

✓ = Compatible • Kompatibel • Compatible • Compatibile

✗ = Incompatible • Unvereinbar • Incompatible • Incompatibile