
EN- Servo Arm - Manual Addendum Air Tractor 1.5M EFL16450 and EFL16475

The location of the linkage in the servo arm was incorrect in the manual.



DE- Servoarm - Zusatz zum Handbuch Air Tractor 1.5M EFL16450 und EFL16475

Die Position des Gestänges am Servoarm war im Handbuch falsch.

FR- Bras de servo - addendum au manuel Air Trac- tor 1.5M EFL16450 et EFL16475

L'emplacement de la tringlerie dans le bras de servo était incorrect dans le manuel.

IT- braccio del servo - addendum al manuale Air Tractor 1.5M EFL16450 e EFL16475

La posizione del rinvio nel braccio del servo indicata nel manuale è errata.

Elevator Höhenruder Gouvernes de profondeur Elevatore		
Rudder Seitenruder Gouverne de direction Timone		
Aileron Querruder Aileron Alettoni		
Flaps Klappen Course des volets Corsa flap		

© 2019 Horizon Hobby, LLC.

E-flite, and the Horizon Hobby logo are trademarks or registered trademarks of Horizon Hobby, LLC.

<http://www.HorizonHobby.com/>

Created 12/2019 64053

EFL16450, EFL16475

Air Tractor 1.5M
